

Sent:  
To:  
Subject:

Hi Joe: Another thought - I don't think Brian should be checking 'no' in the 'hydrology' box as noted below (Sample Pt. 7) in his comments to you regarding my first request for data sheets. If you are not allowed to dig a borehole, you cannot solely rely on surface hydrology indicators to answer 'no', rather the data completion is incomplete and no check should be shown, rather an explanation on why it was incomplete.

From: Kassler, Joseph E LRB [Joseph.E.Kassler@usace.army.mil]  
Sent: Wednesday, February 27, 2013 9:25 AM  
To: Carlson, Greg  
Subject: FW: EPG2 file contents (UNCLASSIFIED)

Hi Greg,

Brian has provided the attached information regarding your previous inquiry. I hope this supplies the answers you needed.

Joe K.

Joseph E. Kassler  
Buffalo District, Corps of Engineers  
Monitoring and Enforcement  
1776 Niagara Street  
Buffalo, NY 14207-3199  
[joseph.e.kassler@usace.army.mil](mailto:joseph.e.kassler@usace.army.mil)  
(716) 877-6923 (work)  
(716) 430-8775 (mobile)

-----Original Message-----

From: Swartz, Brian P LRB  
Sent: Wednesday, February 27, 2013 9:42 AM  
To: Kassler, Joseph E LRB  
Subject: RE: EPG2 file contents (UNCLASSIFIED)

Classification: UNCLASSIFIED  
Caveats: NONE

Joe

I have attached the following:

Datasheets 1 and 2 - not sure where the mix up was but there has always been a datasheet for each plot.

Revised Sampling Plot 7 - no soils were sampled - check mark removed from no hydric soils present, check added for no hydrology in the box entitled Summary of Findings and marked no hydrology present in the Hydrology Section.

Attached completed Sampling Plot 9 datasheet. Not sure how the first two sheets were omitted.

Brian Swartz  
U.S. Army Corps of Engineers  
Buffalo District - Oak Harbor Field Office  
240 Lake Street, Unit D  
Oak Harbor, Ohio 43449  
419 898-3491, 419 898-4292 (fax)